## CALIBRATING PROCEDURE OF FG-5000A

- 1. \* Power off the meter.
  - \* Select the unit switch to " q ".
  - \* Push the button of " ZERO" & " REVERSE " together at the same time. Power " On " the meter, then the meter will into the adjustment mode. After display shows some fix value, then release the button of " ZERO " & " REVERSE ".
- 2. Under adjustment mode, the real zero value will be displayed.
- 3. Once click on " ZERO " Key. " 100.0 " displaying on LCD symbolize that a 100% load will be calibrated at present.( FG-5005, 100 % calibrated load is 5 Kg.)
- 4. Once click on Fast/Slow Key will enter the % load that intend to make the calibration. For example, if enter 40.0, that means the calibrated load will be 5 Kg x 40 % = 2 Kg.
- 5. Once click on " ZERO " button again, the display will show "3000", click on " ZERO " button once again, the display will show " 0". Now the meter has already finished the zero calibration procedures.
- 6. According the above step 4, prepare the standard weight. For example, prepare the 2 Kg weight when select 40% load. Hang the standard weight, the display will show the value near the standard weight. Once click on " ZERO " button, the display will show the value that intend to make the calibration, then display will be flashed. The calibration procedures are finished.
- 7. Take away the standard weight, then power off.