











# WTA Soldering tips

## Chisel shape



A = Width mm  
B = Thickness mm  
C = Length mm







Model	A	B	C	PU	Order No.	Model	A	B	C	PU	Order No.
<b>WTA 1</b> 	1.0	0.5		1	T005 44 141 99	<b>WTA 2</b> 	3.0	0.5		1	T005 44 146 99
<b>WTA 11</b> 	1.0	0.5		1	T005 44 152 99	<b>WTA 3</b> 	6.0	0.5		1	T005 44 147 99
<b>WTA 12</b> 	3.0	0.5		1	T005 44 153 99	<b>WTA 4</b> 	12.5	0.5		1	T005 44 143 99
<b>WTA 1S</b> 	0.5	0.5		1	T005 44 145 99	<b>WTA 5</b> 	18.5	0.5		1	T005 44 144 99

# XH Soldering tips

## Chisel

A = Width mm

B = Thickness mm  
C = Length mm

Model	A	B	C	PU	Order No.	Model	A	B	C	PU	Order No.
<b>XH A</b> 	1.6	0.8	27	1	T005 44 908 99	<b>XH D</b> 	4	0.8	27	1	T005 44 911 99
<b>XH B</b> 	2.4	0.8	27	1	T005 44 909 99	<b>XH HX</b> 	0.8	0.4	35	1	T005 44 912 99
<b>XH C</b> 	3.2	0.8	27	1	T005 44 910 99	<b>XH Spring Barrel</b> 				1	T005 87 687 79






# XHT Soldering tips

## Chisel shape




A = Width mm  
B = Thickness mm  
C = Length mm

Model	A	B	C	PU	Order No.
<b>XHT C</b> 	3.2	1.2	48.0	1	T005 44 804 99
<b>XHT D</b>	5.0	1.2	48.0	1	T005 44 801 99

Model	A	B	C	PU	Order No.
<b>XHT E</b> 	7.6	1.5	48.0	1	T005 44 802 99
<b>XHT F</b> 	9.3	2.0	48.0	1	T005 44 805 99

## Measuring tip

A = Width mm  
B = Thickness mm  
C = Length mm

Model	A	B	C	PU	Order No.
<b>Measuring tip</b> 	0.5		55.0	1	T005 44 803 99

Soldering Stations

Soldering iron and safety rest

Soldering tips and nozzles

Preheating plates

Soldering baths

Circuit board holder

Solder feeder

Hot air heating gun

Temperature measuring

Accessories