SmartFind

smartfind.lenovo.com/accessories



Description	ID	Footnote
E14 G4-21E3 - E14 Gen 4	21E3	P1W45M1. PXE boot supported. Wake On LAN from Hibernation,Power-Off mode.MAC address pass through
E14 G4-21E4 - E14 Gen 4	21E4	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
E15 G4-21E6 - E15 Gen 4	21E6	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
E15 G4-21E7 - E15 Gen 4	21E7	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
L13 Clam G3-21B3 - L13 Clam Gen 3	21B3	P1W45M1. PXE boot supported. Wake On LAN from Hibernation,Power-Off mode.MAC address pass through

L13 Clam G3-21B4 - L13 Clam Gen 3	21B4	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
L13 Yoga G3-21B5 - L13 Yoga Gen 3	21B5	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
L13 Yoga G3-21B6 - L13 Yoga Gen 3	21B6	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
L14 AMD G3-21C5 - L14 Gen 3	21C5	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
L14 AMD G3-21C6 - L14 Gen 3	21C6	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
L14 G3-21C1 - L14 Gen 3	21C1	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
L14 G3-21C2 - L14 Gen 3	21C2	P1W45M1. PXE boot supported. Wake On LAN from Hibernation,Power-Off mode.MAC address pass through
L15 AMD G3-21C7 - L15 Gen 3	21C7	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
L15 AMD G3-21C8 - L15 Gen 3	21C8	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
L15 G3-21C3 - L15 Gen 3	21C3	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
L15 G3-21C4 - L15 Gen 3	21C4	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
P14s G3-21AK MT 2022	21AK	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
P14s G3-21AL MT 2022	21AL	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
T14 G3-21AH - T14 Gen 3	21AH	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through

T14 G3-21AJ - T14 Gen 3	21AJ	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
T14s 2nd Generation- 20WM - T14s Gen 2	20WM	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
T14s 2nd Generation- 20WN - T14s Gen 2	20WN	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
T14s G3-21BR - T14s Gen 3	21BR	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
T14s G3-21BS - T14s Gen 3	21BS	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
T16 G1-21BV - T16 Gen 1	21BV	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
T16 G1-21BW - T16 Gen 1	21BW	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
ThinkBook 14 G4 ABA- 21DK - ThinkBook 14 G4 ABA	21DK	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
ThinkBook 14 G4 IAP- 21DH - ThinkBook 14 G4 IAP	21DH	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
ThinkBook 15 G4 ABA- 21DL - ThinkBook 15 G4 ABA	21DL	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
ThinkBook 15 G4 IAP- 21DJ - ThinkBook 15 G4 IAP	21DJ	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
X1 Carbon G10-21CB - X1 Carbon Gen 10	21CB	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
X1 Carbon G10-21CC - X1 Carbon Gen 10	21CC	P1W45M1. PXE boot supported. Wake On LAN from Hibernation,Power-Off mode.MAC address pass through
X1 Yoga G7-21CD - X1 Yoga Gen 7	21CD	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through

X1 Yoga G7-21CE - X1 Yoga Gen 7	21CE	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
X13 G3-21BN - X13 Gen 3	21BN	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through
X13 G3-21BQ - X13 Gen 3	21BQ	P1W45M1. PXE boot supported. Wake On LAN from Hibernation, Power-Off mode. MAC address pass through