

METRA HIT CAL

3-349-440-03 6/11.12

- Universal calibrator, simulator mA / mV ... V / °C/°F (Pt100/1000, Ni100/1000, thermocouples: J, L, T, U, K, E, S, R, B, N) / 5 ... 2000 Ω
- Frequency generator: 1 Hz ... 1000 Hz
- Ramp and staircase functions
- Easy operation
- Interface and optional METRAwin90-2 calibration software
- Transmitter simulator (sink: 0 ... 24 mA)
- DAkkS calibration certificate included as standard feature
- Rugged, EMC compliant design







System Components and Range of Applications

The **METRAHIT CAL** calibrator functions as a highly accurate calibration and simulation instrument for electrical quantities. As a handheld instrument, it's suitable for precise, on-site calibration and inspection tasks, as well as for test department and laboratory work.

Thanks to its diverse functions, the highly flexible instrument can be used in process engineering, control room and equipment fabrication, general measuring technology and many other applications. As a system component it can always be used in calibration systems for calibrating measuring transducers, buffer amplifiers, transmitters, temperature measuring and recording instruments, controllers, signaling devices and indicators.

If a USB X-TRA interface adapter is plugged on to the instrument (accessory, see page 4), complete calibration procedures and measuring-point oriented calibration cycles can be transferred from a PC, saved to memory and accessed by simply pressing a key. The calibrator setup procedure can thus be significantly shortened, and erroneous settings can be avoided.

Optional METRAwin90-2 software simplifies programming, controls data transfer to the calibrator, receives the measurement data of any interconnected multimeter from a transducer output and executes a comparison of the targeted and the actual situation. Acquired values can be printed out as a calibration report by the PC.

Universal Calibration Standard

Integrated electronics generate mV, V and mA signals. Beyond this, they're capable of simulating thermo-voltages for various types of thermocouples for predefined temperatures (°C or °F), as well as resistance values for various Pt and Ni temperature sensors.

Frequency and Pulse Run Generator

Continuous frequency signals can be transmitted by the **METRAHIT CAL** for testing SPCs, energy metering devices, flow rates and more. Amplitude is adjustable for the generated square-wave pulses, which are used to simulate sensor pulses.

Calibration and Simulation

Measuring transducers with a wide variety of input signals (voltage, thermo-voltage, RTD and 2-wire resistance sensors etc.) can be directly connected and calibrated. If a multimeter is used (e.g. **METRAHITX-TRA**), the respective values can be measured at the measuring transducer's output, transmitted to a PC via an adapter if desired, displayed with the help of optional METRAwin90-2 software and compared with the appropriate calibration specifications. Setpoint values and actual values are displayed, or printed as a certificate. When operated in the "mA sink" mode, the **METRAHIT CAL** simulates a 2-wire transmitter and retrieves the selected current value from the measuring sequence.

Read-Out Modes for Source and Sink Functions

Calibration signals can be read out either manually (numerically with key entries), or automatically by means of intervals with intermediate steps, or as a ramp in a stepless fashion. The METRAHIT CAL can thus be used as a precision pulse

generator for dynamic testing.

Depending upon individual needs, desired dynamic response can be derived from, for example, the full-scale value and the number of intermediate steps (intervals), or rise and dwell periods (ramp). This is especially helpful for long-term testing of laboratory and panel recorders, as well as measuring transducers, and for "one-man" control rooms.

Fixed value

Calibration values are set and read out manually with the help of the instrument's keypad immediately after the calibration function has been selected.

Interval

Continuous read-out of calibration values is accomplished in steps between the minimum and maximum values selected at the device to be calibrated in this read-out mode. The following step can be triggered automatically (time per step: 1 second to 60 minutes) or manually.

Ramp

Continuous read-out of calibration values is accomplished in a stepless fashion between the minimum and maximum values selected at the device to be calibrated in this read-out mode. Ramp duration for rising and falling ramps, as well as dwell time at min. and max. values, can be set within a range of 1 second to 60 minutes.

Temperature Simulation

The ten most common sensor types are available for the simulation of thermo-voltages. Thermo-voltages can be read out with reference to an internal (terminal temperature) or an external reference junction.

Temperature for the external reference junction can be set at the calibrator or with a PC. This eliminates the need to connect the device to be calibrated with the calibrator via the respectively required compensating lead. A copper conductor between the calibrator and the device to be calibrated is sufficient in this case.

Applicable Regulations and Standards

IEC 61010-1/EN 61010-1/ VDE 0411-1	Safety requirements for electrical equipment for measurement, control and laboratory use
EN 60529 VDE 0470, part 1	Test instruments and test procedures Degrees of protection provided by enclosures (IP code)
DIN EN 61 326-1 VDE 0843-20-1	Electrical equipment for measurement, control and labo- ratory use – EMC requirements – Part 1: General re- quirements

Technical Data

Calibration Function	Simulation Range	Resolution 30,000 digits (4¾ places)	Max. nominal Load	Intrinsic Uncertainty	Overload
Direc	t voltage source	;	·	±(% S + mV)	I _{max}
	0±300mV	0.01 mV		0.05 + 0.02	
v	0 3 V	0.1 mV	15 mA	0.05 + 0.2	18 mA
v	010 V	1 mV	TOTIA	0.05 + 2	To IIIA
	015 V	1 mV		0.05 + 2	
duty c	iency generator cycle (pulse-no-pi tude: 10 mV	ulse ratio): 50%	1	±(% S + Hz)	I _{max}
Hz	1 Hz1 kHz	0.11 Hz	15 mA	0.05 + 0.2	18 mA
Curre	nt source		Max. load	±(% S + μA)	
mA	4 20 mA 0 20 mA 0 24 mA	1 μΑ	20 V	0.05 + 2	
Current Sink		·	±(% S + μA)	U _{max}	
	4 20 mA				
mA	0 20 mA	1 μA	$V_{in} = 4 \dots 27 V$	0.05 + 2	27 V
	0 24 mA				
Resis	tance simulatio	n	Sensor current [mA]	±(% S + Ω)	I _{max}
Ω	52000 Ω	0.1 Ω	0.05 <u>0.14</u> 5	0.05 + 0.2	5 mA

Simulator for Temperature Sensors (resolution: 0.1 K)

	Sensor Type Simulation Simulation Intrinsic Over-				
	Sensor Type	Range in °C	Range in °F	Uncertainty	load
	Resistance therm	ometers per IEC	751	±(% S + K)	I _{max}
	Pt100	-200+850	-328+1562	0.1 + 0.5	5 mA
	Pt1000	-200+300	-328+572	0.1 + 0.2	JIIA
	Resistance therm	ometers per DIN	43760	±(% S + K)	I _{max}
	Ni100	-60+180	-76+356	0.1 + 0.5	5 mA
	Ni1000	-60+180	-76+356	0.1 + 0.2	AILC
	RTD sensor current	: 0.05 <u>0.1 4</u>	5 mA	*	
°C / °F	Thermocouples p	er DIN and IEC 58	34-1	∆U in mV *	I _{max}
ပ်	K (NiCr/Ni)	-250+1372	-418+2501		
	J (Fe/CuNi)	-210+1200	-346+2192		
	T (Cu/CuNi)	-270+400	-454+ 752		
	B (Pt30Rh/Pt6Rh)	+500+1820	+932+3308		
	E (NiCr/CuNi)	-270+1000	-454+1832	+ 0,02 mV)	18 mA
	R (Pt13Rh/Pt)	-50+1768	-58+3214		
	N (CU/Cu10)	-270+1300	-454+2372		
	S (Pt10Rh/Pt)	-50+1768	-58+3214		
	L (Fe/CuNi)	-200+900	-328+1652		
	U (Cu/CuNi)	-200+600	-328+1112		

Without internal reference junction;

Relative to fixed external reference temperature and thermovoltage of the thermocouple Internal reference junction: 2 K intrinsic error, external reference junction: entry of -30 ... 60 °C

Key

S = setting value

Reference Conditions

Ambient temperature	+23 °C ±2 K
Relative humidity	40 75%
Battery voltage	3.0 V ±0.1 V

METRA HIT CAL Calibrator

Internal clock

Time format Resolution Accuracy Temp. influence DD.MM.YYYY hh:mm:ss 0.1 s ±1 minute per month 50 ppm/K

Display

LCD panel (65 x 36 mm) with digital display including simulation unit of measure and various special functions

Background Illumination

Background illumination is switched off approximately 1 minute after it has been activated.

Display / Char. neight	7-segment characters
	Main display: 1 x 6 digits, 12 mm
	Auxiliary displays: 2 x 6 digits, 7 mm
Max. resolution	30000
Polarity display	"-" (minus sign) is displayed
Refresh Rate	2 times per second, every 500 ms

Power Supply

Battery	2 AA size batteries, alkaline manganese per IEC LR6 (2 ea. 1.2 V NiMH rechargeable battery also possible)		
Service life	With alkaline manganese (2600 mAh)		
	Calibration Function	Power Consump- tion	Service life
	mV, thermocouple	55 mA	45 h
	15 V	240 mA	10 h
	Ω, RTD	85 mA	30 h
	Sink, 20 mA	310 mA	8 h
	Source, 20 mA	310 mA	8 h
	If voltage drops be instrument is switc		
Battery Indicator	Battery capacity display with battery symbol in 4 segments: . Querying of momentary battery voltage via menu function.		

Power Saving Circuit

The device is switched off automatically if none of the controls are activated for a period of approximately 10 minutes. The simulator is switched off after a period of only 5 minutes (sockets are current and voltage-free). Automatic shutdown can be deactivated.

Power pack socket If the NA X-TRA power pack is plugged in, the installed batteries are disconnected automatically.

Rechargeable batteries can only be recharged externally.

Fuses

Fuse link

FF0,63A/700V, 6,3 mm x 32 mm, min. 1,5 kA switching capacity

Electrical Safety

Protection class Operating voltage Measuring category Pollution degree Test voltage II per EN 61010-1:2001/VDE 0411-1:2002 Max. 50 V I (250 V) 2 500 V~ per EN 61010-1:2001/VDE 0411-1:2002

Electromagnetic Compatibility (EMC)

Interference emission EN 61326-1: 2006 class B Interference immunity EN 61326-1: 2006 EN 61326-2-1: 2006

Data Interface

Туре	Optical via infrared light through the housing	
Data transmission	Serial, bidirectional (not IrDa compatible)	
Protocol	Device specific	
Baud rate	38,400 baud	
Functions	Set/query cal. functions and parameters	
The USB X-TRA plug-in interface adapter (see accessories) is used		
for adaptation to the F	PC's USB port.	

Ambient Conditions

Accuracy range	0 °C +40 °C
Operating temp. range	e −10 °C +50 °C
Storage temp. range	-25 °C +70 °C (without batteries)
Relative humidity	40% 75%, no condensation allowed
Elevation	To 2000 m

Mechanical Design

Dimensions Weight Protection	200 x 87 x 45 mm (without protective rubber holster) Approx. 0.35 kg with batteries IP 54 (pressure equalization via the housing)
	Table Excerpt Regarding Significance of IP Codes

IP XY	Protection against pene-	IP XY	Protection against
(1 st char. X)	tration by solid particles	(2 nd char. Y)	penetration by water
5	Dust protected	4	Splashing water

Scope of delivery:

- METRAHIT CAL calibrator with 2 batteries per IEC LR6 1
- Pair of safety measurement cables (yellow and black) (1.5 m) 1 with 4 mm test probes, 1000 V CAT III, 600 V CAT IV Abbreviated operating instructions 1
- CD ROM with operating instructions in English and German 1
- Protective rubber holster 1
- 1 DAkkS calibration certificate

Guarantee

3 years material and workmanship

1 year for calibration

Accessories

Interface adapter for USB connection

The USB X-TRA bidirectional interface adapter includes the following functions:

- Configure the METRAHIT CAL from a PC. •
- Read data out of memory from the METRAHIT CAL.

The adapter does not require a separate power supply. Its baud rate is 38.400 baud.

A CD ROM is included which contains current drivers for Windows operating systems.



METRAwin90-2 Calibration Software

This software allows for paperless documentation and management of calibration results, the creation of calibration procedures and remote control of the calibrator. METRAHIT CAL sequence controls can be implemented online, or offline after downloading complete calibration procedures.

HitBag Cordura Belt Pouch

For METRAHIT multimeters (with/without protective rubber holster) and METRAport



HC20 hard case

For multimeters (with/without GH18 protective rubber holster) and accessories



Order Information

Description	Туре	Article Number
Calibrator, see scope of delivery	METRAHIT CAL	M244A
Set consisting of METRAHIT CAL handheld calibrator and METRAHIT X-TRA handheld multimeter in HC30 hard case including cable sets, batteries and DAkkS certificates.	METRAHIT CAL Pack	M244B
Accessories	·	
Power pack with broad range input: 90 253 V AC / 5 V DC, CAT IV	NA X-TRA	Z218G
Battery set (4 ea. rechargeable NiMH batteries, 1600 mAh) and charger	1ASi battery set	Z206B
Imitation leather carrying pouch for METRAHIT	F829	GTZ3301000R0003
Cordura belt pouch for METRAHIT multimeters	HitBag	Z115A
Imitation leather ever-ready case with cable compartment	F836	GTZ3302000R0001
Ever-ready case for 2 METRAHITs, 2 adapters and accessories	F840	GTZ3302001R0001
Hard case for 1 METRAHIT and accessories	HC20	Z113A
Hard case for 2 METRAHITs and accessories	HC30	Z113A
Bidirectional interface adapter, IR-USB	USB X-TRA	Z216C
Calibration software for controlling the METRAHIT CAL and for analysis of calibration results	METRAwin90-2	Z211A
Fuse link	FF0,63A/700V	Z109J

For additional information regarding accessories please refer to:

- Measuring Instruments and Testers catalog
- www.gossenmetrawatt.com

Prepared in Germany • Subject to change without notice • PDF version available on the Internet



Südwestpark 15 90449 Nürnberg • Germany Phone +49 911 8602-111 Fax +49 911 8602-777 E-Mail info@gossenmetrawatt.com www.gossenmetrawatt.com