













# CT6 Soldering Tips

## Chisel



A = Width mm  
B = Thickness mm  
C = Length mm

Model	°C	A	B	PU	Order No.	Model	°C	A	B	PU	Order No.
<b>CT6 C7</b> 	370	3.2		1	4CT6C7- 1	<b>CT6 DX8</b> 	425	5.0		1	T005 42 318 99N
<b>CT6 C8</b> 	425	3.2		1 10	4CT6C8- 1 4CT6C8- 1 0	<b>CT6F7 SOLDERING TIP 80MM</b>	425	5.0		1	4CT6F7- 1 4CT6F7- 1 0
<b>CT6 CX7</b> 	370	3.2		1	T005 42 307 99N	<b>CT6F8 SOLDERING TIP 80MM</b>	425	5.0		1	4CT6F8- 1
<b>CT6 D7</b> 	370	5.0		1 10	4CT6D7- 1 4CT6D7- 1 0	<b>CT6-7</b> 				1	T005 61 046 67N
<b>CT6 D8</b> 	425	5.0		1 10	4CT6D8- 1 4CT6D8- 1 0	<b>CT6-9</b> 					T005 61 046 69N
<b>CT6D9 SOLDERING TIP 50MM</b>	425	5.0		1	4CT6D9- 1						
<b>CT6E7</b> 	425	5.0		1	CT6E7						
<b>CT6 E8</b> 	425	7.0		1 10	4CT6E8- 1 4CT6E8- 1 0						
<b>CT6EX8 SOLDERING TIP 70MM</b>					T005 42 328 99N						